

## MOPAR OWNER CONNECT

## SEARCH RESULTS

VIN: 3C4PFABB9FT680025  
Year: 2015  
Vehicle: FIAT FREEMONT SXT (FWD/LHD)  
HATCHBACK

## Questions



Please contact the Chrysler Group Recall Assistance Center at 1-800-853-1403

Results Last Updated: March 21, 2016

## Do you Qualify for Recall Reimbursement?


If you've had a recall on your vehicle and have incurred recall-related costs you'll need to start the reimbursement request process (all on a case-by-case basis).

Safety Recalls (What is a Safety Recall? [Learn More](#))

Status	Chrysler Recall #	NHTSA Recall #	Recall Date	Safety Defect/Non Compliance Description and Safety Risk	Repair Description	Recall Status
 Incomplete	R61	15V-675	October 15, 2015	ANTI-LOCK BRAKE SYSTEM (ABS) CONTROL MODULE MAY HAVE A GROUND WIRE EYELET ON THE RIGHT FRONT SHOCK TOWER THAT ALLOWS WATER TO WICK THROUGH THE GROUND WIRE CASE AND INTO THE ABS MODULE. MOISTURE IN THE ABS MODULE COULD DISABLE THE ABS AND/OR ELECTRONIC STABILITY CONTROL (ESC) SYSTEM(S). THE LACK OF A FUNCTIONING ABS AND/OR ESC SYSTEM(S) COULD CHANGE THE BRAKING AND/OR HANDLING CHARACTERISTICS OF THE VEHICLE AND CAUSE A CRASH WITHOUT WARNING.	SEAL THE GROUND EYELET ON THE RIGHT SHOCK TOWER TO STOP WATER MIGRATION THROUGH THE GROUND WIRE CASE. THE ABS MODULE AND HEADLAMP/DASH WIRE HARNESS MUST ALSO BE INSPECTED FOR MOISTURE AND REPAIRED AND/OR REPLACED IF REQUIRED.	INCOMPLETE BUT REPAIR PARTS ARE AVAILABLE
 Complete	R32	15V-431	June 30, 2015	THE ENGINE BEAUTY COVER MAY DETACH FROM THE ENGINE AND COME IN CONTACT WITH THE CATALYTIC CONVERTER. IF THE ENGINE BEAUTY COVER REMAINS IN CONTACT WITH THE CATALYTIC CONVERTER, UNDERHOOD SMOKE AND/OR A FIRE MAY OCCUR WITHOUT WARNING.	THE ENGINE BEAUTY COVER MUST BE MODIFIED AND A MOUNTING SYSTEM MUST BE INSTALLED.	REPAIRED

Viewing 2 of 2 total recalls

Campaigns (What is a Campaign? [Learn More](#))

Status	Campaign Date	Campaign Description	Repair Description	Comments
 Incomplete	January 23, 2016	REPROGRAM RADIO CONTROL HEAD		INCOMPLETE BUT REPAIR PARTS ARE AVAILABLE

Viewing 1 of 1 total campaigns

## Disclaimer

Notification letters issued prior to 1999 are not available online. Please contact us by email to request a copy.

## Note

Acrobat Reader 5.0 or later is required to view documents.  
[Click here for a free download](#)